



Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: WO/20002BR0170/1

Work Order Type: Weatherization

Audit Name: 20002BR0170

CLIENT INFORMATION

Client Name:

Address:

Client ID: 20002BR0170

Alt. Client ID: Bradley

AGENCY INFORMATION

Agency: Bradley-Cleveland Community Services Agency

Agency Phone: (423) 479-4111

Address: P.O. Box 3297, 155 Sixth Street, S.E.
Cleveland, TN 37320

Fax: (423) 479-4113

Email Address:

Agency Contact: Daugherty, Sam

Work Phone:

Cell Phone: (865) 207-0215

Email Address: samdaugherty@charter.net

Company Name & License Number: _____

Contractor's Signature: _____

COMMENT

Certified Firm/Renovator Required

Client Name:

Client ID: 20002BR0170

Alt. Client ID: Bradley

Work Order (Bid Form)

Work Order Name: WO/20002BR0170/1

Report Run On: 5/25/2010

DOE Weatherization Assistant

Version 8.5.0

Page 1 of 6

Measures

Measure 1 Fix Improper Venting (Wood Stove/Fireplace)

Components

Inspected

Comment Replace Black Pipe, incl El's.
Replace Black Pipe, incl El's. replace outside pie w/proper type approx. 20 ft

☐

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	Equipment	Linear Foot	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	Labor	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Other Detail									
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:

Sub Total:

Field Notes:

Measure 2 Infiltration Redctn

Components

Inspected

Comment mastic 5 vents and 1 return, hook up vent I kit. If heat pupm is fixed, vent currently being used to pull heat from wood stove in basement as auxillary heat, w/s d-&2, w/s attic access, w/s door to basement, repair drywall in br-3 closet after repairing water leak at tub, w-1 bottom pane foggy needs replaced, broken panes in w-2,3,4 repair them,

☐

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
10	Miscellaneous Supplies	Infiltration Reduction	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Other Detail									
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:

Sub Total:

Field Notes:

Client Name:

Client ID: 20002BR0170

Alt. Client ID: Bradley

Work Order (Bid Form)

Work Order Name: WO/20002BR0170/1

Report Run On: 5/25/2010

DOE Weatherization Assistant

Version 8.5.0

Page 2 of 6

Measure 3 DWH Tank Insulation				Components				Inspected	
Comment									
				Estimated		Actual			
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Hot Water Equipment	DHW Tank Insulation	Each	1					
2	Labor	DHW Tank Insulation	Each	1					
Other Detail									
Measure Sub Total:							Sub Total:		
Field Notes:									

Measure 4 DWH Pipe Insulation				Components				Inspected	
Comment									
				Estimated		Actual			
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	DHW Pipe Insulation cost for 10' of wrap	Each	1					
2	Labor	DHW Pipe Insulation	Each	1					
Other Detail									
Measure Sub Total:							Sub Total:		
Field Notes:									

Measure 5 Floor Ins. R-19**Components** basement**Inspected****Comment** add 1118sqft R-19 batts secure w/wire☐

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	Floor Insulation - Fiberglass Batts - R-19	SqFt	1118	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:**Sub Total:****Field Notes:****Measure 6 Install/Replace Heatpump 11.5
(estimated size)****Components** hvac,hvac**Inspected****Comment** replace heat pump, no ductwork needed, CONTRACTOR TO USE MANUAL
J TO GET PROPER SIZE☐

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Heating Equipment	Heatpump - 60 kBtu/h Existing, Consult Manual J Data	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	Heatpump - 60 kBtu/h Existing, Consult Manual J Data	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:**Sub Total:****Field Notes:**

Client Name:

Client ID: 20002BR0170

Alt. Client ID: Bradley

Work Order (Bid Form)

Work Order Name: WO/20002BR0170/1

Report Run On: 5/25/2010

DOE Weatherization Assistant

Version 8.5.0

Page 4 of 6

Measure 7 Install Bathroom Exhaust Fan**Components****Inspected****Comment** Vent Unit to the Exterior

Vent Unit to the Exterior current fan not operating properly

☐

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	Bathroom exhaust fan	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	Labor	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total: **Sub Total:** **Field Notes:****Measure 9 Led Safey EPA-RRP****Components****Inspected****Comment** Certified Firm/Renovator Required☐

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	Misc Material	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor				<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total: **Sub Total:** **Field Notes:**

Client Name:

Client ID: 20002BR0170

Alt. Client ID: Bradley

Work Order (Bid Form)

Work Order Name: WO/20002BR0170/1

Report Run On: 5/25/2010

DOE Weatherization Assistant

Version 8.5.0

Page 5 of 6

Measure 10 PressureRelief Piping Needed				Components				Inspected	
Comment									
				Estimated		Actual			
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	Pressure relief piping	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	Labor	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Other Detail									
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Measure Sub Total:						<input type="text"/>	Sub Total:		<input type="text"/>
Field Notes:									
Work Order Grand Total:						<input type="text"/>	Grand Total:		<input type="text"/>